



SWMS Title:	Use of Electric	Work Vehicle		Description of Task / Activity:		of Task / Activity:		Use of Electric Work \	ehicle	
Partner Site:	All Partner Sites	s								
Qualifications Required			Training Requ	ired to Complet	e Work			Related WHS Legislat	ion	
Refer to <u>HR-PO-13 Licenses & Memberships Policy</u>			Refer to <u>HR-N</u>	City Team Mem N-007 Safety an N-008 Technica	d Compliance	: Training Catalogu	Refer to <u>HSEQ-FM-020 Compliance Obligation Register</u>			
Plant/Equipment Required—Mobile or Static			Plant/Equipm	ent Maintenand	e Checks Red	juired	In the event of an Emergency			
Portable electrical tools and equipment. Portable hand tools. Ladders. PPE. Warning Barricades. Electric Work Vehicle. Trailer		Plant/Equipment Maintenance Checks Required Portable electrical tools and safety equipment to display current test tag. Conduct visual inspection on all portable plant and equipment items prior to use and confirm in serviceable condition.					Refer to site emergency response plan. Call 000 for Police, Fire or Ambulance.			
Developed / R	eviewed by:	ennifer Hoffman	Date	27/02/2023		Approved by:	Pau	ıl Nichols	Date:	27/02/2023

	Minimum Required PPE (Personal Protective Equipment)												
										T?Y	M		
\boxtimes	\boxtimes		\boxtimes	\boxtimes							\boxtimes		

SEQUENCE/TASK DESCRIPTION List the tasks required to perform the activity in the sequence they are carried out.	HAZARDS/RISKS What can harm you—Hazards? What can happen—Risks?	RISK LEVEL	RISK CONTROL MEASURES List the control measures required to eliminate or minimise the risk of injury and detail how the control measures will be put in place.	NEW RISK LEVEL	ACTION BY: Person Responsible
General Working Requirements	Nil		 Sign in to site Notify site/store management that work will be taking place in the area. Discussion to be carried out before work commences to ensure all team members have appropriate PPE in serviceable condition. Review weather conditions prior to work commencing and determine if it is safe to proceed. 		City Team Member /s





SEQUENCE/TASK DESCRIPTION List the tasks required to perform the	HAZARDS/RISKS What can harm you—Hazards?	RISK LEVEL	RISK CONTROL MEASURES List the control measures required to eliminate or minimise the risk of injury and detail how the	NEW RISK	ACTION BY: Person
activity in the sequence they are carried out.	What can happen—Risks?		control measures will be put in place.	LEVEL	Responsible
Set up work area Move tools and equipment to site	Manual Handling Strain / Crush Injury Lacerations Material Weight and size of object Pedestrian and motorised traffic	13 Med (C3)	 Ensure correct manual handling techniques are used e.g. lift with back straight and knees bent. Ensure distances to be travelled are minimised. Barricade and isolate work area to prevent unauthorised access. Special consideration is to be given to appropriately protecting work areas when work is to be performed on sites where children are present. When working with knives or sharp objects cut resistant gloves to be worn. Hi-Vis safety vests to be worn when working in loading dock and motor vehicle trafficable areas. Hi-Vis safety vests to be worn at all times in Coles Distribution Centres. 	5 Low (B2)	City Team Member /s
3. Battery charging and vehicle maintenance	Fire/Explosion Acid burns Electrocution Trips Hazardous substances Chemical spill Entanglement	13 Med (C3)	 Only charge batteries in the designated, well ventilated battery charging area. Do not allow other items/products to be left or stacked in this area. Ensure the manufacturers charging lead and system is used and in good working order. Avoid using vehicle if dashboard switches or controls are damaged. Ensure the load tray cover has been removed to prevent gas build up while charging. Park the vehicle under cover while charging. Do not not allow any ignition sources into close proximity of charging batteries. Maintain clearance from the batteries while charging. Ensure vehicle power is switched off prior to connecting or disconnecting power cable for battery charger. Maintain safe clearances from internal plant electrical connections and leads. Position equipment in a safe location. Ensure main power switch and charger switch is in the "OFF Position" when connecting and disconnecting leads. Never use faulty equipment. If faulty tag it out of service and report immediately to your Line Manager. Allow charger to complete its full charge cycle. 	5 Low (B2)	City Team Member /s





SEQUENCE/TASK DESCRIPTION	HAZARDS/RISKS	RISK	RISK CONTROL MEASURES	NEW	ACTION BY:
List the tasks required to perform the	What can harm you—Hazards?	LEVEL	List the control measures required to eliminate or minimise the risk of injury and detail how the	RISK	Person
activity in the sequence they are carried	What can happen—Risks?		control measures will be put in place.	LEVEL	Responsible
out.			Wear chemical resistant eye protection, gloves, chemical apron and disposable chemical coveralls when undertaking battery maintenance.		
			 Use the chemical spill kit to clean up any battery chemical spills. 		
			 Ose the chemical spill kit to clean up any battery chemical spills. Check water level after a full overnight charge. 		
			 Ensure a (Dry Powder) fire extinguisher is nearby. 		
			Be aware of the nearest First Aid kit.		
			Never conduct battery charging or maintenance near stock. Never charge batteries within 5 matres if imitian sources, best		
			 Never charge batteries within 5 metres if ignition sources, heat, flammable, combustible, oxidising materials, products or stock. 		
			 Only qualified and approved service agents to test, inspect, maintain and repair the electric work vehicle. 		
			 Ensure the vehicle has been effectively isolated with the ignition key 		
			removed and hand brake applied prior to cleaning vehicle.		
			 Maintain safe clearances from moving and rotating parts of the vehicle 		
			and ensure all fitted guards are in place.		
			 Ensure all covers are in place and secured correctly prior to use. 		
			Ensure an covers are in place and secured correctly prior to use.		
			Ensure appropriate PPE is used including a wide brimmed hat and		
	Heat/Cold		sunscreen if working out doors during the day in non-shaded areas.		
			Ensure you are trained and competent in the operation and use of the		
	Crush Injury Material		electric work vehicle.		
			Ensure the operators manual has been read and understood by the driver.		
	Overload or Loss of Load		Ensure the equipment is in a safe working order using the daily pre-		
	Weight and size of object	4.0	operational checklist.	_	
	Collision with Pedestrian and	13	Never use faulty equipment. Tag out of service and report to Line Manager	5	City Team
4. Use of electric work vehicle	motorised traffic	Med	immediately if faulty.	Low	, Member /s
	Slips and Trips	(C3)	Read and understand all warning labels on the vehicle including the	(B2)	, ,
	Striking		capacity plate.		
	Tipping/Uneven surfaces		Ensure tyre pressures are maintained to manufacturers specifications in		
	Struck by moving loads		the operators manual.		
			Reduce speed when turning (particularly on grades) or driving over uneven		
			ground surfaces and grades.		
			Adjust the seat and steering wheel to a comfortable position where Adjust the seat and steering wheel to a comfortable position where		
			possible prior to driving.		





SEQUENCE/TASK DESCRIPTION List the tasks required to perform the	HAZARDS/RISKS What can harm you—Hazards?	RISK LEVEL	RISK CONTROL MEASURES List the control measures required to eliminate or minimise the risk of injury and detail how the	NEW RISK	ACTION BY: Person
activity in the sequence they are carried out.	What can happen—Risks?	22722	control measures will be put in place.	LEVEL	Responsible
			 When moving around blind spots, corners and doorways proceed with caution and sound horn. Plan your route, ensuring a clear path of travel, clear of pedestrians, equipment and stock. Always give way to pedestrians. Keep a distance of 1 metre from pedestrians. Adhere to site traffic requirements. Do not drive vehicle offroad such as rocky environments, soft sand or dirt roads with ruts or uneven road surfaces exceeding 100mm. Ensure the vehicle is fully stationary with the park brake applied and transmission in neutral prior to entering or exiting the vehicle. Park the vehicle on flat ground where possible. All body parts are to remain within the plan view of the cabin. Remain seated while operating the vehicle. In the event of a tip over remain within the vehicle until it has come to a complete stop. Do not leave keys in the ignition while vehicle is unattended. Barricade and isolate working area to prevent unauthorised access where required. Ensure the driving footwell is clear of any grease or oily substances prior to use. Ensure 3 points of contact are maintained when entering or exiting the vehicle. 		
5. Tool cupboards, work plaforms, ladder racks, tool boxes, storage cabinets tools and equipment on electric work vehicle.	Crush Injury Striking Materials and Tools Slips, trips and falls Manual handling	17 High (D3)	 Ensure ladders are placed correctly onto the ladder rack and secured prior to operating the work vehicle. Avoid over reaching when placing or removing ladders from the ladder rack. Ensure tools and equipment are appropriately secured on the rear work platform prior to moving vehicle. Check all tools, equipment, draws, cupboards and storage compartments have been secured prior to operating the vehicle. Take care when heavy braking as items on the load tray may slide and become unstable. 	5 Low (B2)	City Team Member /s





SEQUENCE/TASK DESCRIPTION List the tasks required to perform the activity in the sequence they are carried out.	HAZARDS/RISKS What can harm you—Hazards? What can happen—Risks?	RISK LEVEL	RISK CONTROL MEASURES List the control measures required to eliminate or minimise the risk of injury and detail how the control measures will be put in place.	NEW RISK LEVEL	ACTION BY: Person Responsible
			 Be aware of tool box draws or storage cabinets opening or closing rapidly if parked on inclined areas. Ensure any oxy/acetylene bottles have been appropriately secured in the designated compartment and in an upright position prior to operation of the vehicle. Ensure the vehicle maximum load ratings are not exceeded. Avoid transporting excessively high centre of gravity loads or wide unbalanced loads which can promote instability. Ensure good house keeping in the working area/s around and in the vehicle. Check areas behind or in front of vehicle are clear of any people tools, equipment or other prior to moving. Check revision mirror regularly while operating vehicle. Use site manual handling aids where available and use team lifts where required. 		





SEQUENCE/TASK DESCRIPTION List the tasks required to perform the activity in the sequence they are carried out.	HAZARDS/RISKS What can harm you—Hazards? What can happen—Risks?	RISK LEVEL	RISK CONTROL MEASURES List the control measures required to eliminate or minimise the risk of injury and detail how the control measures will be put in place.	NEW RISK LEVEL	ACTION BY: Person Responsible
6. Changing flat tyres or damaged wheels on electric work vehicle	Crush injury Striking Tipping/Uneven surfaces	13 Med (C3)	 Ensure the vehicle is fully stationary with the park brake applied and transmission in neutral prior to entering or exiting the vehicle. Park the vehicle on flat ground and apply the hand brake. Do not leave keys in the ignition when equipment is unattended. Ensure wheels have been effectively chocked and the vehicle is parked in a safe position out of trafficable areas prior to tyre changing. Ensure the vehicle has been parked in a safe position and barriers used where required. Follow vehicle manufacturer's guidelines and operating instructions when changing wheels. Ensure the vehicle has been effectively blocked underneath prior to changing wheels. 	5 Low (B2)	City Team Member /s





SEQUENCE/TASK DESCRIPTION	HAZARDS/RISKS	RISK	RISK CONTROL MEASURES	NEW	ACTION BY:
List the tasks required to perform the	What can harm you—Hazards?	LEVEL	List the control measures required to eliminate or minimise the risk of injury and detail how the	RISK	Person
activity in the sequence they are carried	What can happen—Risks?		control measures will be put in place.	LEVEL	Responsible
out.					
7. Towing using the electric work vehicle.	Crush injury Struck by moving loads Overload or Loss of Load Weight and size of object Collision with Pedestrian and motorised traffic	17 High (D3)	 Do not modify the vehicle without the approval of service agent. Ensure the tow pin is correctly positioned and secured prior to towing. Handle only stable loads and the load is within the specified limits of the capacity plate. Ensure all loads are appropriately secured prior to moving. Be aware the vehicle towed weight decreases on grades and further decreases when starting on a grade with the maximum draw pull on the name plate to be avoided. Ensure to allow for longer stopping distances when towing trailers and particularly when trailers are loaded. Ensure to allow for longer stopping distances when driving down a slope or incline. Avoid parking on a slope or incline with a trailer attached and if this can't be avoided arrange wheel chocking prior to exiting the vehicle. Ensure to follow the towing section of the vehicle operators manual for safe towing procedures. Ensure the vehicle has adequate towing capacity to safely pull the towed vehicle. Ensure the draw bar or towing strap has a greater capacity than the weight of the vehicle and load being towed. Read and understand the load rating/capacity plate on the vehicle and the vehicle is appropriate for the job task. Operators to read and understand all warning labels on the vehicle including the capacity plate. Keep hands and other body parts clear when connecting and disconnecting the the tow pin. Ensure when connecting or disconnecting towing trailers to the vehicle this is done on flat and even ground. 	5 Low (B2)	City Team Member /s





SEQUENCE/TASK DESCRIPTION List the tasks required to perform the activity in the sequence they are carried out.	HAZARDS/RISKS What can harm you—Hazards? What can happen—Risks?	RISK LEVEL	RISK CONTROL MEASURES List the control measures required to eliminate or minimise the risk of injury and detail how the control measures will be put in place. • Safety footwear.	NEW RISK LEVEL	ACTION BY: Person Responsible
8. Completing the task – exiting the work area	Strains and Sprains Slips, Trips and Falls Sprains or Strains Unauthorised Use of the Pan-brake Folder In the event of an emergency, Store awareness of who is on site	13 Med (C3)	 Correct manual handing techniques e.g lift equipment with back straight and knees bent. Ensure the work shop has been locked after use. Remove tools and equipment from the work area. Remove all waste materials and rubbish from the work area. Identify recyclable materials and arrange drop off to appropriate recycling centre. Waste materials to be disposed of in accordance with jurisdictional waste disposal requirements. Ensure workshop area is clean and tidy. Ensure work shop area is free from slip and trip hazards. Sign out of site. 	6 Low (A3)	City Team Member /s





Induction Statement


I the employee listed below:		
 Have been consulted and understand the requirements of this developed / amended Safe Work the site and understand that I am responsible to work in accordance with this Safe Work Method 		ich I have been engaged on
Name	Signature	Date
Site Manager or Delegate	Signature	Date






Instructions on How to Complete a SWMS:

- Break the job/task down into steps.
- 2. Identify the 'Safety Hazards' associated with each step.
- 3. Use the 'Risk Matrix' to determine the risk of each hazard occurring with no controls in place and record the risk score.
- 4. Consider and document 'Control Measures' used to control the risk, use the 'Hierarchy of Control' to ensure all possible controls have been reviewed, document and record new risk score.
- 5. SWMS developed or reviewed onsite must be approved and signed by the Store Manager or Delegate prior to any works commencing.





Risk Matrix

Step 3 Calculate Risk		SK ASSESSIV	IENT PROCE	55	
		Conse	quence		
Likelihood	1	2	3	4	5
А	1	3	6	10	15
	Low	Low	Low	Medium	High
В	2	5	9	14	19
	Low	Low	Medium	High	Extreme
С	4	8	13	18	22
	Low	Medium	Medium	High	Extreme
D	7	12	17	21	24
	Low	Medium	High	Extreme	Extreme
E	11	16	20	23	25
	Medium	High	Extreme	Extreme	Extreme