

Safe Work Method Statement SWMS – 711



SWMS Title:	Cobwebbing		Description of Task / Activity	Removing co	Removing cobwebs and dust webs from walls and rooves using a cobweb b		
Partner Site:	All Partner Sites						
SWMS prepared by: Donna Smith Posi		Position: Regional HSE Manager CIMS		Date: 09/02/2023 SWMS reviewed by: Paul N			
Authorisation:							
Authorised by: Operational Business Unit Manager or Delegate				ate:			

Risk Matrix

Elimination Substitution Engineering Administration

RISK ASSESSMENT PROCESS Step 1 Determine Step 2 Probability CONSEQUENCE ENVIRON PERSON ASSETS MENT Minor Near **Under \$500 Damage and Minimal** No Miss **Productivity Disruption.** Damage First Aid \$500-1000 Damage and/or Slight Not Likely to **Treatment Production Disruption.** Damage Injury Reversibl MTI or Short \$1000-5000 Damage and/or Possible Term LTI **Production Disruption.** Damage Long Term \$5000-10,000 Damage and/or Serious **Project Contingency Plan Required.** Damage Fatality, More than \$10,000 Damage and/or Major Permanent Large Reorganisation of Project. Damage Disability

Step 3 Calculate Risk						
Consequence						
Likelihood	1	2	3	4	5	
А	1	3	6	10	15	
	Low	Low	Low	Medium	High	
В	2	5	9	14	19	
	Low	Low	Medium	High	Extreme	
С	4	8	13	18	22	
	Low	Medium	Medium	High	Extreme	
D	7	12	17	21	24	
	Low	Medium	High	Extreme	Extreme	
E	11	16	20	23	25	
	Medium	High	Extreme	Extreme	Extreme	

Required PPE (Personal Protective Equipment)								
					8		E'Y	
	\boxtimes		\boxtimes	\boxtimes		\boxtimes		\boxtimes

SWMS No: HSEQ-SWMS-711
Process Area: Health, Safety, Environment & Quality

Uncontrolled when printed or downloaded –
 Commercial in Confidence –
 Copyright © 2023 City Holdings (Aus) Pty Ltd



Safe Work Method Statement SWMS – 711



1. Hazard / Hazardous Event	2. Current Controls				
Preparation/Prestart - General	Using headphones and in-ear listening devices is not permitted at any time whilst on site.				
Preparation/Prestart - Struck by Falling Object	 Check cobweb broom to ensure it is, in good working order, the head is securely attached and there is no damage to or rust in the handle and the handle is not broken. Don't use faulty, broken, or damaged equipment attach an out of service tag and have it replaced Ensure the cobwebbing broom is long enough to perform the cobwebbing task while standing with both feet flat on the floor Perform cobwebbing at a time when there are no customers and minimal staff around. Barricade isle or areas. 				
Preparation/Prestart - Dust	 Only cleaners who have been made aware of the hazards associated with cobwebbing are to carry out this task. P1 dust mask and safety glasses should be worn when cobwebbing to ensure dust, dirt and other objects don't fall in the mouth, nose or eyes. 				
Cobwebbing - Manual Handling	 Ensure the cobwebbing broom is long enough to perform the task with the broom at about a 60 deg angel. Don't use a cobwebbing broom directly above your head. Do not perform cobwebbing for extended periods of time without interval of alternative tasks. 				
3. Additional Information					
For Additional Information contact the HSE Team.					
4. Activity Risk Rating: Low (B2)					